

Benha University

Faculty of Engineering- Shoubra

Electrical Engineering Department



Third year power

23 January 2017

Electrical Machines(2)

-
- Answer all the following questions
 - Illustrate your answers with sketches when necessary.
 - The examination consists of one page
- No. of questions: 3
 - Total Mark: 100 Marks
-

2.a) What are the various methods of starting of three-phase induction motors? Discuss them. **(12 Marks)**

b) A 50 h.p., 3-phase, 4-pole , 50 Hz induction motor has a full-load efficiency of 85%. The friction and windage losses are one-third of the no-load losses and rotor copper losses equal the iron losses at full-load. stator resistance can be neglected. Find

(i) The input power. (ii) Iron losses. (iii) Input power to the rotor. (iv) Output mechanical power. (v) Rotor copper losses. (vi) Full-load slip. (vii) Full-load speed.

(22 Marks)

Solution of Question No. (2) electrical machines(2) 3rd year power

Question No. (2)

a) Method of starting of three-phase induction motors

(i) Direct-on line starting

used for motor up to 10 Hp

(ii) stator resistance starting

(iii) stator reactance starting

(iv) auto transformer starting

(v) star/delta starting

for wound rotor in addition to the previous method control the rotor resistance used in starting induction motor

b) $P_{out} = 50 \times 746 = 37300 \text{ W}$

(i) $P_{in} = P_{out} / \eta$ $P_{in} = 37300 / 0.85 = 43882.4 \text{ W}$

total losses = iron losses + stator copper losses + rotor copper losses
+ friction and windage losses

stator copper losses are neglected as the stator resistance is neglected

No-load losses = iron losses + friction and windage losses

Total losses = input power - output power

total losses = $43882.4 - 37300 = 6582.35 \text{ W}$

No-load losses = iron losses + $(1/3)$ (No-load losses)

iron losses = $(2/3)$ No-load losses

rotor copper losses = iron losses

Total losses = $(7/3)$ iron losses

$6582.35 = (7/3)$ iron losses

(ii) iron losses = 2821 W

(v) rotor copper losses = 2821 W

input power to the rotor = rotor copper losses / s (iii) $P_g = 2821 / 0.068 = 41485.3 \text{ W}$

friction and windage = $(1/2)$ iron losses friction and windage = 1410.5 W

mechanical power = output power + friction and windage

(iv) mechanical power = $37300 + 1410.5 = 38710.5 \text{ W}$

mechanical power = rotor copper losses $(1-s) / s$

$$38710.5 = 2821(1-s)/s$$

$$13.72 = (1-s)/s \quad (vi) \quad s = 0.068$$

$$n_s = 60xf/p \quad n_s = 60 \times 50 / 2 = 1500 \text{ rpm}$$

$$(vii) \quad n = n_s(1-s) = 1500 \times (1 - 0.068) = 1398 \text{ rpm}$$